IB - 260/63 23 September 1963 Copy 4 of

MEMORANDUM FOR: Chief, Manufacturing and Services Division, ORR

ATTENTION

Chief, Cla/PID (NPIC)

SUBJECT: Kuei-yang Cement Plants, Communist China

REFERENCE: (1) ORR Requirement No. RR/118/63

Cla/PID Project No. C 670/63

(2) ORR Requirement No. C-RR3-80,445

CIA/PID Project No. 1081/63

- 1. This memorandum is in answer to the above referenced requirements which request photo enlargements of the two cement plants in Kuel-yang, in addition to information concerning the type of process used, number of kilns and operational status of these plants.
- 2. Three photo enlargements have been included with this memorandum. The first (CIA/PID/IB-P-452/63) covers the area south of Kuei-yang and shows the relative position of the two cement plants. The second and third are photos of the individual plants. The old cement plant (as shown on (CIA/PID/IB-P-453/63) was not operating at the time of photography. This plant has one kiln building but the number of kilns cannot be determined since they are covered. An accurate determination of the type of process used in this plant is not possible. The two siles situated southwest of the stacks could serve as slurry tanks but normally slurry tanks are uncovered. The buildings west of the cement plant appear to be facilities for mechanically processing limestone. The purpose of this processing or the end product derived from it have not been determined.
- 3. The new cement plant (as shown on CIA/PID/IB-P-454/63) is located south of the old one and was not operating at the time of photography. This plant has four rotary kilns but only the two northeasterly kilns appear operational. Slurry tanks are located northwest of the kiln stacks and therefore a wet process is used in this plant. Even though construction was not completed this plant appears to have been in operation since the roofs are dirty, the raw material storage yard shows signs of activity and trucks appear to be loading adjacent to the silos.

Declass Review by NGA

25X1

الماسين الماسين

25X1

25X1

25X

25X1

Approved For Release 2004/05/05 : CIA-RDP78T04743A000200030010-9

						PAGE 2					
this	ected o projec	n extensi	on this project was on should you memorandum and its ereferenced requirement		you have ts enclo	have any further ques			who may be stions concering ared a complete		S
•									-		
		•		,						•	
•						•					
					-						
				•							
enclo	SURES:						. L			,	

25X1

3 Photos (CIA/PID/IB-P-452/63 thru P-454/63)

25X1

4

JLUNE!

25X1

IB - 260/63 23 September 1963 Copy / of 8

MEMORANDUM FOR: Chief, Manufacturing and Services Division, ORR

ATTENTION

Chief, CIA/PID (NPIC)

SUBJECT

FROM

: Kuei-yang Cement Plants, Communist China

REFERENCE

: (1) ORR Requirement No. RR/118/63 CIA/PID Project No. C 670/63

ORR Requirement No. C-RR3-80,445

CIA/PID Project No. 1081/63

- 1. This memorandum is in answer to the above referenced requirements which request photo enlargements of the two cement plants in Kuei-yang, in addition to information concerning the type of process used, number of kilns and operational status of these plants.
- 2. Three photo enlargements have been included with this memorandum. The first (CIA/PID/IB-P-452/63) covers the area south of Kuei-yang and shows the relative position of the two cement plants. The second and third are photos of the individual plants. The old cement plant (as shown on (CIA/PID/IB-P-453/63) was not operating at the time of photography. This plant has one kiln building but the number of kilns cannot be determined since they are covered. An accurate determination of the type of process used in this plant is not possible. The two silos situated southwest of the stacks could serve as slurry tanks but normally slurry tanks are uncovered. The buildings west of the cement plant appear to be facilities for mechanically processing limestone. The purpose of this processing or the end product derived from it have not been determined.
- β . The new cement plant (as shown on CIA/PID/IB-P-454/63) is located south of the old one and was not operating at the time of photography. This plant has four rotary kilns but only the two northeasterly kilns appear operational. Slurry tanks are located northwest of the kiln stacks and therefore a wet process is used in this plant. Even though construction was not completed this plant appears to have been in operation since the roofs are dirty, the raw material storage yard shows signs of activity and trucks appear to be loading adjacent to the silos.

i_ i			
F 1.	Š		

25X1

هٔ			25>
		PAGE 2	05)
5X1	4. The analyst on this project contacted on should this project. This memorandum and it answer to the above referenced requi	ou have any further questions concering so enclosures are considered a complete	25>
			25>
	ENCLOSURES: 3 Photos (CIA/PID/IB-P-452/63 thru	P-454/63)	





